


CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-11170
Quad Newark East
SPO map # 06-07-33
Hundred Pencader
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: ORP Industrial Park
2. STREET LOCATION: 796 Old Baltimore Pike
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure _____ b) district _____ c) archaeological site _____
d) other industrial complex
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field x b) cultivated field _____ c) woodland x
d) scattered buildings x e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known x b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Carol A. Benenson/ Mark A. Bower TEL. # (215) 561-1050
YOUR ADDRESS: 1316 Arch Street, Philadelphia, PA 19107
ORGANIZATION (if any) KKFS DATE: March 1987

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

Located along Old Baltimore Pike is this 1920s industrial building of rusticated cast stone and concrete masonry unit (cmu) construction. It has had several one-story additions to its east side and rear. A large cmu warehouse was constructed on the site in the mid-20th century.

10. Comprehensive Planning:

- a. Time Period(s) 1880-1940
- b. Cultural Concept Economic and Cultural Concepts

11. Evaluation:

- a. Settlement & Development
- b. Cultural Historic & Ethnic Issues
- c. Built Environment
- d. Material Culture
- ☒ e. not eligible

USE BLACK INK ONLY

Survey: Name/Title Benenson/Bower


Date 3/87

BAHP: Name/Title _____

Date _____

CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685




Form CRS-1
FOR OFFICE USE ONLY

CRS # N-11170
Quad Newark East
SPO map # 06-07-33
Hundred Pencader
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 796 Old Baltimore Pike

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape rectangular
stories 2 1/2
bays 5
wings east side 2 story addition; rear one story privy; rear one story pump house; west side one story cmu addition.
- b) Structural system masonry & frame
- c) Foundation
materials cmu
basement none
- d) Exterior walls
materials rusticated
color(s) white, dark green trim
- e) Roof
shape; materials gabled; asphalt
cornice overhang
dormers none
chimney location(s) interior east end
- f) Windows
spacing regular
type single and paired, mostly 6/6 double hung; bulk window at 1st floor
trim molded lintels on main facade and rear
shutters
- g) Door
spacing
type single leaf glazed and paneled entrance to office; garage door
trim pent over garage entrance entrance; side entrance into west addition, modern
- h) Porches none
location(s)
materials
supports
trim
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good x deteriorated _____

remarks:

4. INTEGRITY: a) original site x b) moved _____
c) if moved, when and from where _____
d) list major alterations and dates (if known)

5. DATE OF INITIAL CONSTRUCTION: c.1925

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn _____ b) carriage house _____ c) garage _____ d) privy _____
e) shed x f) greenhouse _____ g) shop _____ h) gardens _____
i) icehouse _____ j) springhouse _____ k) other industrial building


describe: industrial building - c. 1950s cmu warehouse, one story, 12 light
industrial sash; shed - clapboarded, German wood siding

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


9. Primary References: (include location of reference).

10. Surveyor: Benenson/Bower - KKFS Date of Form: March 1987

USE BLACK INK ONLY




Top: looking southeast; Bottom: looking northeast



CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



FORM CRS-2

FOR OFFICE USE ONLY


CRS # N-11169
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Workers House #3
2. STREET LOCATION: 694 Old Baltimore Pike
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure x b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field x b) cultivated field _____ c) woodland x
d) scattered buildings _____ e) densely built up x f) other swamp
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known x b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Carol A. Benenson/ Mark A. Bower TEL. # 215-561-1050
YOUR ADDRESS: 1316 Arch Street, Philadelphia, Pennsylvania 19107
ORGANIZATION (if any) KKFS Inc. DATE: March 1987

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

This cottage is representative of small-scale workers' housing from the 1920s. It is considerably altered and not of architectural significance.

10. Comprehensive Planning:

- a. Time Period(s) 1880-1940
- b. Cultural Concept Landscape

11. Evaluation:

- a. Settlement & Development
- b. Cultural Historic & Ethnic Issues
- c. Built Environment
- d. Material Culture
- ☒ e. not eligible

INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

Survey: Name/Title Benenson/Bower


Date 3/87

BAHP: Name/Title _____

Date _____

CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



Form CRS-1
FOR OFFICE USE ONLY

CRS # N-11169
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 694 Old Baltimore Pike

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape rectangular, gable front
stories 1 1/2
bays 3 by 3 deep
wings rear one-story

b) Structural system frame

c) Foundation
materials concrete
basement none

d) Exterior walls
materials asphalt shingles
color(s) brick red


e) Roof
shape; materials gabled; asphalt shingles
cornice box
dormers none
chimney location(s) centered to side, interior; ridge line of rear wing

f) Windows
spacing regular
type 1/1 and 2/2 double hung 1st floor; 6/6 in dormer
trim simple wood
shutters none

g) Door
spacing off center
type 4-light glazed and 2-paneled, single leaf
trim simple wood surround

h) Porches
location(s) front
materials wood with asphalt roof
supports square posts
trim none

i) Interior details (if accessible)



SKETCH PLAN

USE BLACK INK ONLY

3. CONDITION: good x deteriorated

remarks: _____

4. INTEGRITY: a) original site x b) moved _____

c) if moved, when and from where

d) list major alterations and dates (if known)

reclad with asphalt singles

5. DATE OF INITIAL CONSTRUCTION: c. 1920

6. ARCHITECT/BUILDER:

7. RELATED OUTBUILDINGS:

a) barn b) carriage house c) garage x d) privy x

e) shed f) greenhouse g) shop h) gardens

j) icehouse j) springhouse k) other

describe: garage - asphalt shingled, gabled frame structure, double

swinging doors on strap hinges; privy - frame, asphalt shingles to match house.

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).

10. Surveyor: C. Benenson/M. Bower - KKFS Date of Form: March 1987

USE BLACK INK ONLY




Top: looking southwest; Bottom: looking south



CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-11168
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Workers House #2
2. STREET LOCATION: 690 Old Baltimore Pike
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure ☒ b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field ☒ b) cultivated field _____ c) woodland ☒
d) scattered buildings _____ e) densely built up ☒ f) other swamp
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known ☒ b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Carol A. Benenson/Mark A. Bower TEL. # 215-561-1050
YOUR ADDRESS: 1316 Arch Street, Philadelphia, Pennsylvania 19107
ORGANIZATION (if any) KKFS Inc. DATE: March 1987

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

This dwelling, considerably altered, is representative of small-scale workers' housing from the second quarter of the 20th century. It is not of architectural significance.

10. Comprehensive Planning:

- a. Time Period(s) 1880-1940
- b. Cultural Concept Landscape

11. Evaluation:

- a. Settlement & Development
- b. Cultural Historic & Ethnic Issues
- c. Built Environment
- d. Material Culture
- ☒ e. not eligible

INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

Survey: Name/Title Benenson/Bower Date 3/87
BAHP: Name/Title _____ Date _____

**CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM**

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685




Form CRS-1
FOR OFFICE USE ONLY

CRS # N-11168
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 690 Old Baltimore Pike

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape **Rectangular**
stories **1**
bays **2**
wings **none**
- b) Structural system frame
- c) Foundation
materials **cmu**
basement **none**
- d) Exterior walls
materials **asphalt**
color(s) **tan**
- e) Roof
shape; materials **gabled; asphalt**
cornice **simple**
dormers **none**
chimney location(s) **exterior side**
- f) Windows
spacing **regular**
type **1/1 double hung**
trim
shutters
- g) Door
spacing **off center**
type **glazed and paneled single leaf**
trim **simple wood surround**
- h) Porches
location(s) **none**
materials
supports
trim
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good x deteriorated _____
remarks: _____

4. INTEGRITY: a) original site x b) moved _____
c) if moved, when and from where _____
d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: 2nd quarter of the 20th century

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn _____ b) carriage house _____ c) garage _____ d) privy x
e) shed 2 f) greenhouse _____ g) shop _____ h) gardens _____
i) icehouse _____ j) springhouse _____ k) other _____

describe: shed - frame construction; shed - corrugated metal
privy - corrugated metal

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

This building appears to have been a small worker's cottage dating from the second quarter of the 20th century.

9. Primary References: (include location of reference).

10. Surveyor: C. Benenson/ M. Bower - KKFS Date of Form: March 1987

USE BLACK INK ONLY




Top: looking south; Bottom: looking southeast



CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



FORM CRS-2

FOR OFFICE USE ONLY

CRS # N-11167
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Workers House #1

2. STREET LOCATION: 688 Old Baltimore Pike

3. OWNER'S NAME: _____ TEL. # _____

ADDRESS: _____

4. TYPE OF LOCUS: a) structure x b) district _____ c) archaeological site _____
d) other _____

5. SURROUNDINGS OF LOCUS: (check more than one if necessary)

a) fallow field x b) cultivated field _____ c) woodland x

d) scattered buildings _____ e) densely built up x f) other swamp

6. THREATS TO LOCUS: (check more than one if necessary)

a) none known x b) zoning _____ c) roads _____ d) developers _____

e) deterioration _____ f) other _____

7. REPRESENTATION ON OTHER SURVEYS:

TITLE: _____ # _____

TITLE: _____ # _____

TITLE: _____ # _____

8. YOUR NAME: Carol A. Benenson/Mark A. Bower TEL. # 215-561-1050


YOUR ADDRESS: 1316 Arch Street, Philadelphia, Pennsylvania 19107

ORGANIZATION (if any) KKFS Inc. DATE: March 1987

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

This cottage, representative of 1920's modest workers' housing, is not of architectural significance.

10. Comprehensive Planning:

- a. Time Period(s) 1880-1940
- b. Cultural Concept Landscape

11. Evaluation:

- a. Settlement & Development
- b. Cultural Historic & Ethnic Issues
- c. Built Environment
- d. Material Culture
- ☒ e. not eligible

INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

Survey: Name/Title Benenson/Bower


Date 3/87

BAHP: Name/Title _____

Date _____

CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685




Form CRS-1
FOR OFFICE USE ONLY

CRS # N-11167
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 688 Old Baltimore Pike

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape rectangular
stories 1 1/2
bays 2
wings none
- b) Structural system frame
- c) Foundation
materials cmu
basement none
- d) Exterior walls
materials asbestos
color(s) grey
- e) Roof
shape; materials gable; asphalt with tin flashing
cornice overhang
dormers none
chimney location(s) center of ridge line
- f) Windows
spacing regular
type 1/1 double hung
trim lipped lintels
shutters none
- g) Door
spacing off center
type single leaf with glazing
trim lipped lintel
- h) Porches
location(s) front
materials frame
supports wood posts
trim none
- i) Interior details (if accessible)



SKETCH PLAN

USE BLACK INK ONLY

3. CONDITION: good x deteriorated _____

remarks: _____

4. INTEGRITY: a) original site x b) moved _____

c) if moved, when and from where _____

d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: c.1920

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn _____ b) carriage house _____ c) garage x d) privy x

e) shed _____ f) greenhouse _____ g) shop _____ h) gardens _____

i) icehouse _____ j) springhouse _____ k) other _____

describe: garage - cmu construction

privy - frame construction

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).

10. Surveyor: C. Benenson/ M. Bower - KKFS Inc. Date of Form: March 1987

USE BLACK INK ONLY




Top: looking southwest; Bottom: looking southeast



CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-11166
Quad Newark East
SPO map # 06-07-33
Hundred White Clay
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Reese Residence
2. STREET LOCATION: 431 Old Baltimore Pike
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure x b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field _____ c) woodland _____
d) scattered buildings x e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known _____ b) zoning _____ c) roads x d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Carol A. Benenson/ Mark A. Bower TEL. # 215-561-1050
YOUR ADDRESS: 1315 Arch Street, Philadelphia, Pennsylvania 19107
ORGANIZATION (if any) KKFS Inc. DATE: March 1987

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

This dwelling is representative of the typical gabled cottage of the first half of the 20th century. However, this is not an outstanding example due to its alterations and additions.

10. Comprehensive Planning:

- a. Time Period(s) 1880-1940
- b. Cultural Concept Landscape

11. Evaluation:

- a. Settlement & Development
- b. Cultural Historic & Ethnic Issues
- c. Built Environment
- d. Material Culture
- ☒ e. not eligible


INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

Survey: Name/Title Benenson/Bower Date 3/87
BAHP: Name/Title _____ Date _____

CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685




Form CRS-1
FOR OFFICE USE ONLY

CRS # N-11166
Quad Newark East
SPO map # 06-C7-33
Hundred White Clay
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 431 Old Baltimore Pike

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape rectangular
stories 1 1/2
bays 2
wings side addition
- b) Structural system frame
- c) Foundation
materials cmu
basement yes
- d) Exterior walls
materials aluminum siding
color(s) white
- e) Roof
shape; materials gabled; asphalt
cornice simple overhang
dormers done
chimney location(s) exterior front towards west side
- f) Windows
spacing regular
type single and paired 1/1 double hung
trim simple surrounds
shutters black aluminum louvered
- g) Door
spacing side
type single leaf, modern glazed
trim simple surround
- h) Porches
location(s) front, enclosed
materials aluminum siding
supports frame construction
trim none
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good x deteriorated

remarks: _____

4. INTEGRITY: a) original site x b) moved

c) if moved, when and from where

d) list major alterations and dates (if known)

5. DATE OF INITIAL CONSTRUCTION: c. 1930

6. ARCHITECT/BUILDER:

7. RELATED OUTBUILDINGS:

a) barn b) carriage house c) garage x d) privy

e) shed x f) greenhouse g) shop h) gardens

i) icehouse j) springhouse k) other

```
describe:      shed- frame construction
```

garage - cmu construction


8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

This house was built on the site of the 1868 Reese residence but is, in fact a 1930s house.

9. Primary References: (include location of reference).

10. Surveyor: C. Benenson/M. Bower - KKFS Date of Form: March 1987

USE BLACK INK ONLY




Top: looking southwest; Bottom looking south



CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-3994
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Sexton's House, Salem M.E. Church
2. STREET LOCATION: 473 Salem Church Road
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure x b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field _____ c) woodland x
d) scattered buildings x e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known _____ b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other new church construction
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Carol A. Benenson/Mark A. Bower TEL. # 215-561-1050
YOUR ADDRESS: 1316 Arch Street, Philadelphia, Pennsylvania 19107
ORGANIZATION (if any) KKFS Inc. DATE: March 1987

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

Located within a site that includes Salem M.E. Church and cemetery is this Sexton's House. The building is a mid-19th century vernacular frame dwelling of modest proportions and style. The building is slated for demolition as part of the Church's plans to develop the site for expanded church facilities.

10. Comprehensive Planning:

- a. Time Period(s) 1830-1880
- b. Cultural Concept People

11. Evaluation:

- a. Settlement & Development
- b. Cultural Historic & Ethnic Issues
- c. Built Environment
- d. Material Culture
- ☒ e) not eligible

USE BLACK INK ONLY

Survey: Name/Title Benenson/Bower

Date 3/87

BAHP: Name/Title _____

Date _____

CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



Form CRS-1
FOR OFFICE USE ONLY

CRS # N-3994
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 473 Salem Church Road

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape L
stories 2
bays 2
wings ell to south

b) Structural system frame

c) Foundation
materials rubblestone
basement none

d) Exterior walls
materials asphalt shingles
color(s) white


e) Roof
shape; materials gable; asphalt
cornice box
dormers none
chimney location(s) center of ridge line

f) Windows
spacing regular
type 2/2 double hung with 1/1 double hung in the wing
trim simple
shutters none

g) Door
spacing off center
type glazed single leaf
trim simple

h) Porches
location(s) front and south side of addition
materials frame; addition porch enclosed with screens
supports 2 x 4
trim none

i) Interior details (if accessible)



SKETCH PLAN

USE BLACK INK ONLY

3. CONDITION: good x deteriorated

remarks: _____

4. INTEGRITY: a) original site b) moved

c) if moved, when and from where

d) list major alterations and dates (if known)

5. DATE OF INITIAL CONSTRUCTION: c.1850

6. ARCHITECT/BUILDER:

7. RELATED OUTBUILDINGS: none

a) barn b) carriage house c) garage d) privy

e) shed f) greenhouse g) shop h) gardens

i) icehouse j) springhouse k) other

```
describe:
```

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

Built in the mid-19th century, this structure served as a Sexton's House to Salem M.E. Church and more recently has served as a Sunday School. The Church plans to demolish this structure as part of the site development for new church facilities.

9. Primary References: (include location of reference).

Pomeroy & Beers. Atlas of the State of Delaware. Philadelphia:1868.

Interview with Rev. Donald J. Hurst, March 1987.

10. Surveyor: C. Benenson/ M. Bower - KKFS Date of Form: March 1987

USE BLACK INK ONLY




Top: looking south; Bottom: looking northwest



CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-3993
Quad Newark East
SPO map # 06-07-33
Hundred White CLay Creek
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Salem United Methodist Church
2. STREET LOCATION: 469 Salem Church Road
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure x b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field _____ c) woodland x
d) scattered buildings x e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known _____ b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other new church construction
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Carol A. Benenson/ Mark A. Bower TEL. # 215-561-1050
YOUR ADDRESS: 1316 Arch Street, Philadelphia, Pennsylvania 19107
ORGANIZATION (if any) KKFS Inc. DATE: March 1987

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

Salem M. E. Church is part of a site that includes a cemetery and Sexton's House/Sunday School(to be demolished). The church was built in 1807 as a one-story, two-bay deep sanctuary. It was repaired in 1848 and 1853(1884 according to Scharf). The victorian door hood likely was added during these mid-century repairs. In 1904 the church was enlarged into a two-story, three-bay structure with office space partitioned out of the first floor and a sanctuary above. In the late 1950s a substantial brick addition was added across the rear which has marred the building's integrity.

10. Comprehensive Planning:

- a. Time Period(s) 1770-1830; 1830-1880;1880-1940; 1940-present
- b. Cultural Concept People; Landscape

11. Evaluation:

- a. Settlement & Development
- b. Cultural Historic & Ethnic Issues
- c. Built Environment
- d. Material Culture
- ☒ e. not eligible

USE BLACK INK ONLY

Survey: Name/Title Benenson/Bower


Date 3/87

BAHP: Name/Title

Date

CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685




Form CRS-1
FOR OFFICE USE ONLY

CRS # N-3993
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 469 Salem Church Road

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape rectangular
stories 2
bays 2
wings large rear addition
- b) Structural system brick
- c) Foundation
materials stucco over rubble
basement none
- d) Exterior walls
materials brick
color(s) red
- e) Roof
shape; materials gabled; asphalt
cornice box
dormers none
chimney location(s) in modern addition
- f) Windows
spacing regular
type segmental openings, rectangular lights; stained glass
trim segmental brick arches, wood sills
shutters
- g) Door
spacing central
type double 4-paneled door
trim Victorian flat door hood with brackets
- h) Porches none
location(s)
materials
supports
trim
- i) Interior details (if accessible)



SKETCH PLAN

USE BLACK INK ONLY

remarks: badly repointed

4. INTEGRITY: a) original site x b) moved _____
c) if moved, when and from where _____
d) list major alterations and dates (if known) c.1904, enlargement;
c. 1950, addition.

5. DATE OF INITIAL CONSTRUCTION: 1807

6. ARCHITECT/BUILDER:

7. RELATED OUTBUILDINGS:

a) barn _____ b) carriage house _____ c) garage _____ d) privy _____
e) shed x f) greenhouse _____ g) shop _____ h) gardens _____
i) icehouse _____ j) springhouse _____ k) other cemetery, sexton's house (see N-3994)
describe: shed - frame construction

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

Salem M.E. Church was built in 1807, before which meetings were held in the residence of William Wright and Mr. Hersey. The land for the church was deeded to the trustees by Robert McFarlin, schoolmaster on May 12, 1807 according to Rev. Hurst (Oct. 15, 1805, according to Scharf). This church was a parent church to other Methodists in Christiana and Red Lion. Salem M.E. was connected with the Cecil County Circuit until 1864 and in 1867 formed part of the Christiana Circuit. By the early 1880s the church had 50 communicants and 70 pupils in its Sunday School under the superintendence of John W. Dayett. The trustees at that time were: Jonathan Groves, G.W. Groves, James A. Lee, Benjamin Lee, John W. Dayett, John Hall,

9. Primary References: (include location of reference).

Interview with Rev. Donald J. Hurst, March 1987.
Scharf, J. Thomas. History of Delaware 1609-1888. Vol.II. Port Washington, NY:
Kennikat Press, 1888.

8. Continued.

Isaac C. Snitcher, Paul Gillis, and Henry Singers. Expanded in 1904 and again in the late 1950s, the church now accommodates 264 members.

10. Surveyor: C. Benenson/ M. Bower - KKFS Inc. Date of Form: March 1987

USE BLACK INK ONLY




Top: looking north; Bottom: historic photo of church ca. 1900



CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-6774
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: J. Groves Farm
2. STREET LOCATION: 332 Old Baltimore Pike
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure _____ b) district _____ c) archaeological site _____
d) other agricultural complex
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field x c) woodland _____
d) scattered buildings _____ e) densely built up _____ f) other development
6. THREATS TO LOCUS: (check more than one if necessary) ☒
a) none known _____ b) zoning _____ c) roads _____ d) developers x
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Carol A. Benenson/Mark A. Bower TEL. # 215-561-1050
YOUR ADDRESS: 1316 Arch Street, Philadelphia, PA 19107
ORGANIZATION (if any) KKFS Inc. DATE: March 1987

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



9. COMMENTS:

Consider the following:

- relationship to setting
- associated traditions or stories
- noteworthy features
- comparison with others in area

Although this house may at one time have been a handsome Italianate structure, it has undergone a considerable loss of integrity due to residing, removal of the porch and ornament, and addition of the mid-20th century colonial porch. The bank barn, of mid-19th century origins, is of note. It has been expanded with several modern additions and given a modern gambrel roof.

10. Comprehensive Planning:

- Time Period(s) 1830-1880
- Cultural Concept Economic & Cultural Trends; Landscape

11. Evaluation:

- Settlement & Development
- Cultural Historic & Ethnic Issues
- Built Environment
- Material Culture
- ☒ not eligible

INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

Survey: Name/Title Benenson/Bower Date 3/87
BAHP: Name/Title _____ Date _____

CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685




Form CRS-1
FOR OFFICE USE ONLY

CRS # N-6774
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 332 Old Baltimore Pike

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape rectangular
stories 2
bays 3
wings 3-story rear wing, altered
- b) Structural system frame
- c) Foundation
materials concrete
basement yes
- d) Exterior walls
materials aluminum siding
color(s) white
- e) Roof
shape; materials hipped; asphalt
cornice simple box
dormers none
chimney location(s) middle, interior end
- f) Windows
spacing regular
type paired 4/4 double hung, 6/6 on side, modern 1/1 in rear wing
trim wood, simple
shutters none
- g) Door
spacing central
type single leaf 6-panel, appears original
trim 4-light transom, 3-light sidelights
- h) Porches
location(s) front
materials wood
supports turned posts
trim none
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good x deteriorated _____
remarks: _____

4. INTEGRITY: a) original site x b) moved _____
c) if moved, when and from where _____
d) list major alterations and dates (if known) residing,
removal and replacement of front porch

5. DATE OF INITIAL CONSTRUCTION: c. 1850

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn x b) carriage house _____ c) garage x d) privy _____
e) shed x f) greenhouse _____ g) shop _____ h) gardens _____
i) icehouse _____ j) springhouse _____ k) other corn crib, chicken house

describe: barn - mid-19th century, rubblestone foundation, peg construction,
beaded vertical board siding, wood shake gambrel roof, cmu additions;
garage - frame construction, corrugated metal roof; shed - rubblestone
foundation, matchboard siding, paneled metal roof; corn crib - on cement
piers, vertical board siding; chicken house - frame construction, vertical board
siding.

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY
ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

This property was owned by Jonathan Groves as of 1851, although he appears on
atlases as early as 1849. Groves was born near Odessa and worked on his parents
farm until he bought his own where he resided for nearly 50 years. He was elected
to serve one term in the State Legislature. A trustee of Salem M.E. Church,
Groves was buried in the churchyard upon his death in 1894.

9. Primary References: (include location of reference).

Pomeroy & Beers. Atlas of the State of Delaware. Philadelphia: 1868.

Runk, J.M. and Co. Biographical and Genealogical History of the State of
Delaware. Vol.1. Chambersburg, PA: J.M. Runk & Co. 1899.

Scharf, J. Thomas. History of Delaware 1609-1888. Vol.II. Port Washington,
NY: Kennikat Press, 1888.

10. Surveyor: C. Benenson/M. Bower - KKFS Inc. Date of Form: March 1987

USE BLACK INK ONLY



Top: looking south; Bottom: looking northeast



J. GROVES FARM N-6774




Top: looking east; Bottom: looking north



CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



FORM CRS-2

FOR OFFICE USE ONLY


CRS # N-11165
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: West Wind
2. STREET LOCATION: 311 Old Baltimore Pike
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure _____ b) district _____ c) archaeological site _____
d) other agricultural complex
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field x b) cultivated field x c) woodland _____
d) scattered buildings _____ e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known x b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Carol A. Benenson/ Mark A. Bower TEL. # (215)561-1050
YOUR ADDRESS: 1316 Arch Street, Philadelphia, PA 19107
ORGANIZATION (if any) KKFS DATE: March 1987

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

Built on the foundations of an early farmhouse is the brick house erected in 1937. The house is colonial in its use of first floor multiple windows, pedimented frontispiece, and gabled dormers. The house itself is not an outstanding example of architectural craft from the 1930s compared to others in the state such as the George N. Short farm near Smyrna (K-3837). The outbuildings, erected in 1939, are of interest as a collection of period structures, but are not of an age or exceptional merit to justify National Register eligibility.

10. Comprehensive Planning:

- a. Time Period(s) 1880-1940
- b. Cultural Concept Economic and Cultural Trends

11. Evaluation:

- a. Settlement & Development
- b. Cultural Historic & Ethnic Issues
- c. Built Environment
- d. Material Culture
- e. not eligible

INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

Survey: Name/Title Benenson/Bower


Date 3/87

BAHP: Name/Title _____

Date _____

CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



Form CRS-1
FOR OFFICE USE ONLY

CRS # N-11165
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 311 Old Baltimore Pike

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape rectangular
stories 2 1/2
bays 2
wings side sun room

b) Structural system brick masonry

c) Foundation
materials cmu
basement yes

d) Exterior walls
materials tapestry brick
color(s) red


e) Roof
shape; materials gabled; asphalt
cornice box
dormers front and back, asphalt sided, gabled, box cornice
chimney location(s) exterior side

f) Windows
spacing regular
type tripartite at 1st, double at 2nd and dormer
trim brick lintels and sills
shutters none

g) Door
spacing centered
type Tudoresque with pedimented frontispiece, full doric columns,
trim vertical boards, leaded glass lights

h) Porches
location(s) raised terrace, concrete pad with tapestry brick foundation
materials
supports
trim

i) Interior details (if accessible) rusticated cast stone fireplace, relatively
flat molded surrounds, side stair with slender spindles



SKETCH PLAN

USE BLACK INK ONLY

3. CONDITION: good x deteriorated

remarks: _____

4. INTEGRITY: a) original site x b) moved _____

c) if moved, when and from where

d) list major alterations and dates (if known)

5. DATE OF INITIAL CONSTRUCTION: c.1937

6. ARCHITECT/BUILDER:

7. RELATED OUTBUILDINGS: all c. 1939

a) barn x b) carriage house c) garage x d) privy

e) shed x f) greenhouse g) shop h) gardens

i) icehouse _____ j) springhouse _____ k) other tenant house; dairy; corn crib
garage- German wood siding, windows on far gabled end, sliding cross-
describe: braced doors, asphalt roof; barn - cmu base, vertical board siding,
gambrel roof, Dutch doors in gambrel end, sliding doors on side; dairy - cmu,
gabled roof, very deteriorated; shed - machinery shed, frame construction,
corrugated metal roof and side walls, enclosed garage section with swinging doors;
shed - machinery shed, pole construction, corrugated metal, deteriorated

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

This farmhouse was built by Roger E. Wooleyhan in 1937 on the foundations of the earlier W. Heisler residence. The outbuildings for this farm that had cows and horses were erected in 1939. "West Wind" was a name given to the farm by the owner's wife.

9. Primary References: (include location of reference).

Interview with Mr. Roger E. Wooleyhan, owner, March 1987.

7. cont. corn crib - on grade, vertical board, ventilators; chicken house - vertical board, very deteriorated; rooster house - vertical board siding, very deteriorated; tenant house - 1 1/2 story, 2 bay gabled cottage, cmu base, frame construction, asbestos shingles, porch - front with chamfered posts, asphalt roof, gabled front, cross-gabled across rear, 6/6 double hung sash, simple wood surrounds, 4 light, 2 paneled side door, chimney along rear ridge

10. Surveyor: Benenson/ Bower - KKFS Date of Form: March 1987

USE BLACK INK ONLY



Top: looking north; Bottom: looking southeast






Top: tenant house looking west; Bottom: dairy barn & corn crib looking west



CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



FORM CRS-3

FOR OFFICE USE ONLY


CRS # 11164
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Woodshade
2. STREET LOCATION: 279 Old Baltimore Pike
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure _____ b) district _____ c) archaeological site _____
d) other dwelling complex
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field _____ c) woodland _____
d) scattered buildings x e) densely built up x f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known x b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Carol A. Benenson/Mark A. Bower TEL. # (215) 561-1050
YOUR ADDRESS: 1316 Arch Street, Philadelphia, PA 19107
ORGANIZATION (if any) KKFS DATE: March 1987

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

This dwelling is a representative example of the gabled cottage that was a popular house form in the first half of the 20th century.

10. Comprehensive Planning:

- a. Time Period(s) 1880-1940
- b. Cultural Concept Landscape

11. Evaluation:

- a. Settlement & Development
- b. Cultural Historic & Ethnic Issues
- c. Built Environment
- d. Material Culture
- ☒ e. not eligible

Survey: Name/Title Benenson/Bower

Date 3/87

BAHP: Name/Title _____

Date _____

CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER DELAWARE 19901
(302) 736 - 5685



Form CRS-1
FOR OFFICE USE ONLY

CRS # 11164
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 279 Old Baltimore Pike

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape rectangular
stories 1 1/2
bays 2
wings front enclosed porch, rear
addition

b) Structural system frame

c) Foundation
materials cmu
basement yes

d) Exterior walls
materials asbestos shingle
color(s) white


e) Roof
shape; materials gabled; asphalt
cornice simple box
dormers none
chimney location(s) exterior side

f) Windows
spacing regular
type 1/1 double hung
trim molded lintels
shutters none

g) Door
spacing side entrance into front enclosed porch
type glazed and paneled
trim simple wood

h) Porches
location(s) front enclosed
materials cmu foundation, asbestos shingles
supports frame construction
trim none

i) Interior details (if accessible)



SKETCH PLAN

USE BLACK INK ONLY

3. CONDITION: good x deteriorated

remarks:

4. INTEGRITY: a) original site x _____ b) moved _____

c) if moved, when and from where

d) list major alterations and dates (if known) 1960 alterations

to front and rear additions

5. DATE OF INITIAL CONSTRUCTION: c. 1925

6. ARCHITECT/BUILDER:

7. RELATED OUTBUILDINGS:

a) barn b) carriage house c) garage x d) privy

e) shed f) greenhouse g) shop h) gardens

i) icehouse j) springhouse k) other

describe: 2 garages - c. 1925, frame, aluminum siding, sliding door

- с. 1960, смu

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).

10. Surveyor: Benenson/Bower - KKFS Date of Form: March 1987

USE BLACK INK ONLY




Top: looking north; Bottom: looking west



CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-11163
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Southgate/Red Roof
2. STREET LOCATION: 101 Old Baltimore Pike
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure _____ b) district _____ c) archaeological site _____
d) other dwelling complex
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field _____ c) woodland x
d) scattered buildings x e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known x b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Carol A. Benenson/ Mark A. Bower TEL. # 215-561-1050
YOUR ADDRESS: 1316 Arch Street, Philadelphia, Pennsylvania 19107
ORGANIZATION (if any) KKFS Inc. DATE: March 1987

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

This colonial house was built in 1942 on the site of a 19th century property known as Southgate/Red Roof. This common house form is not of significance or an age to merit National Register eligibility.

10. Comprehensive Planning:

- a. Time Period(s) 1940-present
- b. Cultural Concept Landscape

11. Evaluation:

- a. Settlement & Development
- b. Cultural Historic & Ethnic Issues
- c. Built Environment
- d. Material Culture
- e. ☒ not eligible

USE BLACK INK ONLY

Survey: Name/Title Benenson/Bower


Date 3/87

BAHP: Name/Title _____

Date _____

**CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM**

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 736 - 5685




Form CRS-1
FOR OFFICE USE ONLY

CRS # N-11163
Quad Newark East
SPO map # 06-07-33
Hundred White Clay Creek
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 101 Old Baltimore Pike

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape rectangular
stories 2
bays 2
wings rear one-story shed room
- b) Structural system frame
- c) Foundation
materials concrete
basement yes
- d) Exterior walls
materials aluminum siding
color(s) white
- e) Roof
shape; materials gabled; asphalt
cornice plain box
dormers none
chimney location(s) exterior rear, centered
- f) Windows
spacing regular
type 1/1 double hung
trim panned with aluminum
shutters plastic louvered, wood-grained
- g) Door
spacing side
type single leaf 4-panel
trim simple
- h) Porches
location(s) front
materials wood, enclosed with glass and clapboarding
supports wood frame
trim quarter round molding at cornice
- i) Interior details (if accessible)



SKETCH PLAN

USE BLACK INK ONLY

3. CONDITION: good x deteriorated _____
remarks: _____

4. INTEGRITY: a) original site x b) moved _____
c) if moved, when and from where _____
d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: 1942

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:
a) barn _____ b) carriage house _____ c) garage x d) privy _____
e) shed _____ f) greenhouse _____ g) shop _____ h) gardens _____
i) icehouse _____ j) springhouse _____ k) other chicken house
describe: garage - concrete and frame construction, asbestos shingles,
sliding doors; asphalt gabled roof, contemporary with house;
chicken house - concrete foundation, plywood walls, tar paper roof.

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).

10. Surveyor: C. Benenson/ M. Bower - KKFS Date of Form: March 1987

USE BLACK INK ONLY



Top: looking west; Bottom: looking northeast

